

School Site - Lead Sampling	0-5 PPB	5-10 PPB	10-15 PPB	Notes:
Addams	10			
Barton	11			
Birney	10	1		Sample taken in cafeteria - food prep sink faucet 6.1 PPB
Bixby	10			
Bryant	7	2		Samples taken in cafeteria 5.1 & 5.9 PPB
Burbank	7	1		Sample taken in main bldg. custodian office 6.4 PPB
Burcham	12	1		Sample taken in cafeteria - stove faucet 10.0 PPB
Chavez	9			
Cubberley	13			
Dooley	9			
Edison	12			
Emerson	9			
Franklin	10			
Fremont	5	1		Sample taken outside -west 5.1 PPB
Gompers	4	1		Sample taken cafeteria - outside 6.1 PPB
Grant	14			
Harte	11	1		Sample taken bldg. outside near girls RR 6.9 PPB
Herrera	8			
Holmes	6			
Hoover	6			
Jefferson	8			
Jordan Plus	18	1		Sample taken outside north next to track 6.4 PPB
Keller	10			
Kettering	8	2		Samples taken in cafeteria 5.7, 8.2 and 19.8 PPB (latter reading on fixture that was inoperable prior to test and then was capped off as precaution to remain out of service)
Lakewood	7			
Lincoln	11	2		Sample taken in cafeteria 5.4 PPB and bldg. 2 room 9 - 7.0 PPB
Lindsey	10			
Longfellow	14			
Lowell	9	2		Samples taken in bldg A hallway 7.1 PPB , bldg. B outside 7.0 PPB
MacArthur	6			
Madison	5			
Mann	11			
McKinley	13			
Millikan	22	2		Samples taken in bldg. 200 hallway 6.7 PPB and bldg. 700 hallway 5.1 PPB
Monroe	4	1		Sample taken in bldg. D 7.5 PPB
Muir	13			
Riley	5			
Robinson	6			

School Site - Lead Sampling	0-5 PPB	5-10 PPB	10-15 PPB	Notes:
Sato	7	1		Sample taken in bldg. 400 room 402 - 5.8 PPB
Smith	10			
Stevenson	10			
Tincher	9	2	1	Samples taken in bldg. A (10.1 PPB) , bldg. C (8.4 PPB), bldg. E cafeteria (7.1 & 15.7 PPB). Latter reading on kitchen hose faucet, used for cleaning pots, exempt from testing under state guidelines but replaced as a precaution to achieve retest of 5.2 PPB.
Webster	11			
Willard	7			